<u>e Work</u>

Inspection Report for Flood Damage W						
Date :/2						
1. Name of P	IUs :-	E.E	RWD	Muzatta	m Pur	west.
2. Name of B	Block :-	Sah	ie began	1		
3. Name of R	toad :- l	_068-	L041-	to Banga	a NIJa	tom
A. For Road						
1. Damage L	ocation/Chaina	.ge	:- ch	20500 kuto	2:900	km '
2. Damage L	ength		:- 30	M0.		
3. Nature of	Damage		:- P	ort sreaches		
4. Details of	Restoration Wo	orks	:-			
(i) Mate	erial being used	in Rest	oration wo	orks :-		
(ii) Equi	(ii) Equipments/Tools being used in Restoration Works:-					
(iii) Proc	(iii) Procedure taken up un Restoration works :-					
(iv) Rest	ored Length	:-	30.0	M		
B. For Bridg	e					
1. Damage I	ocation/Chaina	age	:-			
2. Damage Length			:- ₁			
3. Nature of	3. Nature of Damage		:-		<i>V</i>	- 1

Material being used in Restoration works: (i)

Equipments/Tools being used in Restoration Works :-

(iii) Procedure taken up un Restoration works :-

(iv) Restored Length

4. Details of Restoration Works

Signature of JE/