

Inspection Report for Flood Damage Work

Date :-...../...../2024

1. Name of PIUs :- E.E RWD Muzaffarpur West.
2. Name of Block :- Sahabganj
3. Name of Road :- Trinut bandh Road To Jg Roop chauri.

A. For Road

1. Damage Location/Chainage :- 0.00 km to 0.200 km @
2. Damage Length :- 53 m
3. Nature of Damage :- Road cutting due to Flood/ Breaches
4. Details of Restoration Works :-
(i) Material being used in Restoration works :- Brick Pats, Sand Filling, Sand Bag
(ii) Equipments/Tools being used in Restoration Works :- Tractor, Roller, and JCB
(iii) Procedure taken up un Restoration works :- Departmental
(iv) Restored Length :- 53 m

B. For Bridge

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
(i) Material being used in Restoration works :-
(ii) Equipments/Tools being used in Restoration Works :-
(iii) Procedure taken up un Restoration works :-
(iv) Restored Length :-

N.A

Signature of JE/

AE/

EE

Executive Engineer
RWD Works Division
Muzaffarpur East-2
(Name of Inspecting Officer)