

## Inspection Report for Flood Damage Work

Date :-...../...../2024

1. Name of PIUs :- Executive Engineers RWD Muzaffarpur West
2. Name of Block :- Motipur
3. Name of Road :- NH-28 Motipur chowk - Anjana'kot via Bathar Road.
- A. For Road

1. Damage Location/Chainage :- North side Approach of Bridge
2. Damage Length :- 30 metre
3. Nature of Damage :- Approach collapse
4. Details of Restoration Works :-

- (i) Material being used in Restoration works :- Brick bats, Sand bag, Rabbish, piling etc. Bamboo
- (ii) Equipments/Tools being used in Restoration Works :- Tractor, Roller & JCB
- (iii) Procedure taken up un Restoration works :- Departmental
- (iv) Restored Length :- 30 metre

### B. For Bridge

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-

- (i) Material being used in Restoration works :-
- (ii) Equipments/Tools being used in Restoration Works :-
- (iii) Procedure taken up un Restoration works :-
- (iv) Restored Length :-

Signature of JE/

AE/

EE

Executive Engineer  
RWD Work Division  
Muzaffarpur East  
(Name of Inspecting Officer)