INSPECTION REPORT FOR MOTORABLE WORK

	OKT FOR MOTORABLE WORK
Name of PIUs:-	Ihandla Mul
Name of Block/Road :- Moelf	epin/ B Talla O
A. For Road	epul GTSNY Road to mm Gry Roa
1. Damage Location/Chainage:- 2	05 m
2. Damage Length :- 34 m	
3. Nature of Damage (Length Wise)	(i) Breach: 34 m
	(ii) Crust Damage :-
	(iii) Only Flank Damage
whether traffic fully/Partialiy obstruc	cted:- Fully
1. Details of Restoration:-	
i) Material Being Used in Restoration	on: Brick Vel
ii) Equipment/Tools Being Used in I	Restoration Works: - JCB & Treeden
iii) Restored Length	In open Area:- upen
	In open Area:- uper In habitation Area:- t/A
iv) If Restoration work done in habit	ration Area give Reason :-
3. For Bridge (Size of Bridge/Cu	livert)
1) Damage Location/Chainage :-	
2) No. of Span Damage :-	
3) Length of Span :-	
Nature of Damage (Pier/Abuttmen	
/ing Wall/Approach Road Damage)	(= 1) - 2, 1 1 2 1 1 2 2 2, 2 2 11
) Details of Restoration :-	
Material Being Used in Restoration	ı :-
Equipment/Tools Being Used in R	estoration Works :-
i) Restored Length :-	
	34
verall Grade of Restoration work	(Satisfactory/Unsatisfactory) :-

Assolution of

Signature of Inspector

Xecutive af Suppleer

Rural Works Department

Works Division, Jaynagar