

INSPECTION REPORT FOR MOTORABLE WORK

e of PIUs :-

me of Block / Road :- NH-77 Lajma chonk to Bali Road.

A. For Road

1. Damage location / Chainage :- 0-1.50KM ; Lat- 26.50455°, Long-85.409408

2. Damage Length :- 20M.

3. Nature of Damage (Length Wise)

(i) Breach :-

(ii) Crust Damage :- ~~partially~~ 20M

(iii) Only Flank Damage -

Whether Traffic Fully / Partially obstructed :- Partially obstructed.

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Break bales, Rabbis and bamboo

(ii) Equipment / Tools Being used in Restoration Work :- Tractor, G-JCB,

(iii) Restored Length

In open Area :- 20M.

In Habitation Area :-

(iv) If Restoration Work Done in habitation Area give Reason :- N.A.

B. For Bridge (Size of Bridge / Culvert)

(1) Damage Location / Chainage :-

(2) No. of Span Damage :-

(3) Lenth of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/ Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment / Tools Being used in Restoration Work :-

(iii) Restored Length

Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :-

Signature of Inspector
(Official Seal)