

# INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Sri Arinash Kumar, 22, P.W.D., Sitamarhi  
Name of Block / Road :- Araria to enduse IT

## A. For Road

1. Damage location / Chainage :-

CH - 130 km

2. Damage Length :- 0.022 km

3. Nature of Damage ( Length Wise)

(i) Breach :- 0.022 km

(ii) Crust Damage :-

(iii) Only Flank Damage

Whether Traffic Fully / Partially obstructed :- fully obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Portland Cement, crushed

(ii) Equipment / Tools Being used in Restoration Work :- J.C.B., Tractor

(iii) Restored Length

In open Area :-

In Habitation Area :-

(iv) If Restoration Work Done in habitation Area give Reason :-

## B. For Bridge (Size of Bridge / Culvert)

(1) Damage Location / Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage ( Pier/Abutment/  
Wing Wall/ Approach Road Damage ) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment / Tools Being used in Restoration Work :-

(iii) Restored Length

Overall Grade of restoration Work ( Satisfactory/Unsatisfactory ) :-

12/11/24  
Signature of Inspector  
(Official Seal)