

# INSPECTION REPORT FOR MOTORABLE WORK

PIUs :-

of Block / Road :- Fatehpur Sarbanpur warpa Badali Kantauli Bhasar path

## A. For Road

1. Damage location / Chainage :-

Lat - 26.758011 Long - 85.431722 Alt - 725.10754

2. Damage Length :- 0.029 Km

3. Nature of Damage ( Length Wise)

(i) Breach :- 0.029 Km

(ii) Crust Damage :-

(iii) Only Flank Damage

Whether Traffic Fully / Partially obstructed :- partially obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Solides bat, Rubbish

(ii) Equipment / Tools Being used in Restoration Work :- J.C.B., Tractor

(iii) Restored Length

In open Area :- 0.029 Km

In Habitation Area :-

(iv) If Restoration Work Done in habitation Area give Reason :-

## B. For Bridge (Size of Bridge / Culvert )

(1) Damage Location / Chainage :-

(2) No. of Span Damage :-

(3) Lenth of Span :-

(4) Nature of Damage ( Pier/Abuttment/  
Wing Wall/ Approach Road Damage ) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment / Tools Being used in Restoration Work :-

(iii) Restored Length

Overall Grade of restoration Work ( Satisfactory/Unsatisfactory ) :-

Signature of Inspector  
(Official Seal)