

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- *Sh. Avibast Kumar, D2, R.M.O., Sidhartha*
Name of Block / Road :- *Bambarga Rajmura R.2.0 road to Indurua*

A. For Road

1. Damage location / Chainage :- *CH 0.700 km*

2. Damage Length :- *0.010 km*

3. Nature of Damage (Length Wise)

(i) Breach :- *0.010 km*

(ii) Crust Damage :-

(iii) Only Flank Damage

Whether Traffic Fully / Partially obstructed :- *fully obstructed*

4. Details of Restoration :-

(i) Material Being Used in Restoration :- *Gravel, Betts, subball*

(ii) Equipment / Tools Being used in Restoration Work :- *J.L.B., Tractor*

(iii) Restored Length

In open Area :- *0.010 km*

In Habitation Area :-

(iv) If Restoration Work Done in habitation Area give Reason :-

B. For Bridge (Size of Bridge / Culvert)

(1) Damage Location / Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/ Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment / Tools Being used in Restoration Work :-

(iii) Restored Length

Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :-

LD
4.11.24
Signature of Inspector
(Official Seal)