

SPECTION REPORT FOR MOTORABLE WORK

11US :- Sri Avinash Kumar, O.R. R. 600, Sittamarthi
of Block / Road :- 17 Larua Dularpur to curda chotauna

A. For Road

1. Damage location /Chainage :- Lat - 26.757448 Long - 85.48417 CH - 85010890

2. Damage Length :- 0.0301m

3. Nature of Damage (Length Wise)

(i) Breach :-

(ii) Crust Damage :- 0.03%

(iii) Only Flank Damage

Whether Traffic Fully / Partialy obstructed :- *partially obstructed*

4. Details of Restoration :-

(i) Material Being Used in Restoration :- *Senecio hats, Rubbish, Bamboo*

(ii) Equipment / Tools Being used in Restoration Work :- J.C.B, Tractor

(iii) Restored Length

In open Area :-

In Habitation Area :-

(iv) If Restoration Work Done in habitation Area give Reason :-

B. For Bridge (Size of Bridge / Culvert)

(1) Damage Location / Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/ Wing Wall/ Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment / Tools Being used in Restoration Work :-

(iii) Restored Length

Overall Grade of restoration Work (Satisfactory/Unsatisfactory) :-

Signature of Inspector
(Official Seal