



## Inspection Report for Flood Damage work

Date

- |              |   |   |
|--------------|---|---|
| 1            | Name of PIUS  | Gaya  |
| 2            | Name of Block/Road                                  | Bodhgaya /Mankosi To Ghoghariya   |
| A For Road   |   |   |
| 1            | Damage Location/Chainage                            | At. Chanage 7.2 Km Damage   |
| 2            | Damage Length                                       | 12 Mtr.   |
| 3            | Nature of Damage                                    | Damaged Due to Flood  |
| 4            | Details of Restoration Works                        |   |
|              | i material Being used in Restoration Works          | Local Sand GSB, <del>Sand Bag</del>   |
|              | ii Equipments/Tools being used in Restoration Works | Tractor, JCB, Dumpher & Roller  |
|              | iii Procedure Taken up in Restoration Works         | Filling the Local Sand at Damaged Location & Spreading the GSB over it and than compacting it with the Roller |
|              | iv Restored length                                  | 12 Mtr.   |
| B For Bridge |   |   |
| 1            | Damage Location/Chainage                            | N/A   |
| 2            | Damage Length                                       | N/A   |
| 3            | Nature of Damage                                    | N/A   |
| 4            | Details of Restoration Works                        |   |
|              | i material Being used in Restoration Works          | N/A   |
|              | ii Equipments/Tools being used in Restoration Works | N/A   |
|              | iii Procedure Taken up in Restoration Works         | N/A   |
|              | iv Restored length                                  | N/A   |

  
Signature of JE/AE/EE

  
25/11/2024  
Signature (Name of Inspector)  
कार्यपालक अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रमंडल नवादा।