

## Inspection Report of Flood Damage work

Name of PIUs:- RWD Works Division, Darbhanga

Name of Block/Road:- Mohanpur, PWD se Bishanpur Beri se matiaur  
se matiaur chamer tola yadav tola  
kali maudir gachhi

### A. For Road

1. Damage Location Chainage:- 0.00 km to 0.160 km.

2. Damage Length :- 10.75 m

3. Nature of Damage :- Breach

#### 4. Details of Restoration Works

i. Material being used in Restoration works:-

ii. Equipment's /Tools being used in Restoration works:-

iii. Procedure taken up in Restoration works:-

iv. Restored Length:-

Brick batts (165.250 m<sup>3</sup>)

Tractor

Brick batt filling

10.75 m

### B. For Bridge

1. Damage Location Chainage:-

2. Damage Length :-

3. Nature of Damage :-

#### 4. Details of Restoration Works

i. Material being used in Restoration works:-

ii. Equipment's /Tools being used in Restoration works:-

iii. Procedure taken up in Restoration works:-

iv. Restored Length:-

H/A

Found work satisfactory

WU  
21/11/24  
JE  
Signature of JE/AE/EE

hukari  
21.11.24  
A.E

21.11.24  
EE

K  
21.11.24  
Signature

(Name of Inspection)

Suman Kumar  
E.E. Dalsingh Sarani