

Inspection Report of Flood Damage work

Name of PIUs:- RWD Works Division, ^{Patori} Darbhanga

Name of Block/Road:- M. Nagar, Siwaisingpur Se Nawada

A. For Road

1. Damage Location Chainage:- 2.00 km to 2.01 km, 2.74 km to 2.76 km

2. Damage Length :- 15.50 m

3. Nature of Damage :- Breach

4. Details of Restoration Works

i. Material being used in Restoration works:-

Brick balls (41.380 m³)

ii. Equipment's /Tools being used in Restoration works:-

Tractor

iii. Procedure taken up in Restoration works:-

Brick ball filling

iv. Restored Length:-

15.50 m

B. For Bridge

N.A

1. Damage Location Chainage:-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works


i. Material being used in Restoration works:-

ii. Equipment's /Tools being used in Restoration works:-

iii. Procedure taken up in Restoration works:-

iv. Restored Length:-

Found work satisfactory.


Signature of JE/AE/EE


E.E


Signature

(Name of Inspection)

Suman Kumar
E.E, Dalsingh Sarai