

## Inspection Report of Flood Damage work

Name of PIUs:- RWD Works Division, Darbhanga  
Name of Block/Road:- Patori  
M. Nagar, Mohiuddinagar Bazar Bishanpur  
Berri to Saunapur

### A. For Road

1. Damage Location Chainage:- 2.45 km, 5.50 km, 5.76 km
2. Damage Length :- 157.00 m
3. Nature of Damage :- Breach
4. Details of Restoration Works

- i. Material being used in Restoration works:-
- ii. Equipment's /Tools being used in Restoration works:-
- iii. Procedure taken up in Restoration works:-
- iv. Restored Length:-

Brick batts (623.450 m<sup>3</sup>)  
Tractor  
Brickbatt filling  
157.0 m

### B. For Bridge

1. Damage Location Chainage:-
  2. Damage Length :-
  3. Nature of Damage :-
  4. Details of Restoration Works
- i. Material being used in Restoration works:-
  - ii. Equipment's /Tools being used in Restoration works:-
  - iii. Procedure taken up in Restoration works:-
  - iv. Restored Length:-

N.A

H/A

Found work satisfactory

Signature of JE/AE/EE  
21/11/24 21.11.24  
A.E.

21.11.24  
EE

Signature  
21/11/24

(Name of Inspection)

Suman Kumar  
E.E., Dal Singh Sarai