

# INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- P.W.D work Division, Pattisera, Kharagpur, Garapur

Name of Block/Road :- Motorable Road from Babhanga Munchawk

A. For Road to Babhanga Gosiyasi Gola

1. Damage Location / Chainage:- 0.30 km to 1.80 km

2. Damage Length 729 m

3. Nature of Damage (Length wise)

(i) Breach :-

(ii) Crust Damage :- 729 m

(iii) Only Flank Damage

Whether Traffic Fully/Partialily Obstructed :-

4. Details of Restoration

(i) Material Being Used in Restoration :- Brick bat, GSB grd

(ii) Equipment/ Tools being Used in Restoration Works :- Tractor, J.C.B, Roller

(iii) Restored Length

In Open Area :- 729 m

In Habitation Area :-

(iv) If Restoration work done in habitation Area Give Reason :-

B. For Bridge (Size of Bridge/Culvert)

1. Damage Location / Chainage:-

2. No. of Span Damage

3. Length of Span

4. Nature of Damage (Pier/ Abutment/Wing wall/Approach Road Damage)

5. Details of Restoration

(i) Material Being Used in Restoration :-

(ii) Equipment/ Tools being Used in Restoration Works :-

(iii) Restored Length

In Open Area :-

In Habitation Area :-

Overall Grade of Restoration Work (Satisfactory/Unsatisfactory)

18/11/24  
JK

18/11/24  
Signature of Inspector  
(Officail Seal)