

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- R.W.D work Division (Kathisara) Kharagpur, Garabur

Name of Block/Road :- Motorable Road from Pipariya to Walipur

A. For Road Pakor

1. Damage Location / Chainage:- 0 KM. to 0.800 KM

2. Damage Length 599m

3. Nature of Damage (Length wise)	(i) Breach :- 475m
	(ii) Crust Damage :- 124m
	(iii) Only Flank Damage

Whether Traffic Fully/Partialily Obstructed :-

4. Details of Restoration

(i) Material Being Used in Restoration :- Brack bats, GSB grit

(ii) Equipment/ Tools being Used in Restoration Works :- Tractor, J.C.B, Roller

(iii) Restored Length	In Open Area :- 599m
	In Habitation Area :-

(iv) If Restoration work done in habitation Area Give Reason :-

B. For Bridge (Size of Bridge/Culvert)

1. Damage Location / Chainage:-

2. No. of Span Damage

3. Length of Span

4. Nature of Damage (Pier/ Abutment/Wing wall/Approach Road Damage)

5. Details of Restoration

(i) Material Being Used in Restoration :-

(ii) Equipment/ Tools being Used in Restoration Works :-

(iii) Restored Length	In Open Area :-
	In Habitation Area :-

Overall Grade of Restoration Work (Satisfactory/Unsatisfactory)

Rajesh
18/11/24
JC

Signature of Inspector
(Officail Seal)