INSPECTION REPORT FOR MOTOR

Name of PIUs :- PET A
Name of PIUs:- EE RUD LIOYKS DIVISION Anonia
10001 / LO25 - Kankludia to Maachhi
1. Damage Location/Chainage:- D. En al.
2. Damage Length:- 22 m
3 Nature of Dames of
(ii) Crust Damage :-
whether traffic fully/Partially obstructed:-
4. Details of Restoration:
(i) Material Being Used in Restoration: Brick both, Socal Sand, bamboo to both
(ii) Equipment/Tools Being Used in Pentaration Walter Tools Being Used in Pentaration Walter Tools
(ii) Equipment/Tools Being Used in Restoration Works:- アカロイヤン、JCO
(iii) Restored Length In open Area:-
(iv) If Pestoration and 1 in habitation Area:-
(iv) If Restoration work done in habitation Area give Reason:-
B. For Bridge (Size of Bridge/Culvert)
(1) Damage Location/Chainage :-
(2) No. of Span Damage :-
(3) Length of Span :-
(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-
(5) Details of Restoration:-
i) Material Being Used in Restoration:-
ii) Equipment/Tools Being Used in Restoration Works:-
iii) Restored Length :-
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Sakstactory
Signature of Inspector (Official Seal)
06/11/1y