

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RHD, Works Division- Area
 Name of Block/Road :- Anania/ LOS- To 70 Bathur bari East

A. For Road

1. Damage Location/Chainage :- 0.980 km

2. Damage Length :- 30.0 mtr.

3. Nature of Damage (Length Wise) (i) Breach :- Breach damage
 (ii) Crust Damage :- Crust damage
 (iii) Only Flank Damage :-

whether traffic fully/Partially obstructed :- fully

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Local Sand, Bamboo, EC Bag, Brick Bed, etc

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with front loader, Roller, JCB,

(iii) Restored Length

In open Area :- 30.0 mtr.

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Signature of Inspector
 (Official Seal)

Cupre
11/11/20
an