## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:- EE RWA WOYKS Devision Arong	]
Name of PIUs: - EE RWA WOYKS Dirining Arnala  Name of Block/Road: - Kunsakatta 1 Loss - forbingery to Sinward  A For Pond	
A. For Road	1
	-
1. Damage Location/Chainage: - 0.600 km 1.000 km 1.400 km	
2. Damage Length: 41m, 16.5m, 21m (78.5m) 3. Nature of Damage (Length Wise) (i) Breach: One och Cutting	
3. Nature of Damage (Length Wise) (i) Breach: One och Cutting	
(ii) Crust Damage: - Grust Samage (iii) Only Flank Damage: - flank Cutting	
(iii) Only Flank Damage: - flank Cutting	
whether traffic fully/Partially obstructed:- fully	
4. Details of Restoration:-	
(i) Material Being Used in Restoration: - Incal Sand, Ec bogs, Pambro-	ruch
(i) Material Being Used in Restoration: Lucal Sand, Ec bogs, Panhos, (ii) Equipment/Tools Being Used in Restoration Works: Tractor-Trulley, Polla,	JU
(iii) Restored Length In open Area: 78.5 m	
In habitation Area :-	
(iv) If Restoration work done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span:-	
(4) Nature of Damage (Pier/Abuttment/	
Wing Wall/Approach Road Damage):-	
(5) Details of Restoration:-	and the second second
(i) Material Being Used in Restoration:-	
(ii) Equipment/Tools Being Used in Restoration Works:-	
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Satisfactory	
10 4 2104	

Signature of Inspector
(Official Seal)