INSPECTION REPORT	FOR MOTORA	ABLE WORK
IUs:- EF ALLA		Λ .

Name of Pius:- EF Days 400 100 100 Access
Name of Plus: - EE RWD War us Division Amonia Name of Block/Road: - Palosi / PMGSY Hatiya to Kulohiya Road A. For Road
A. For Road
1. Damage Location/Chainage:- 0.100 Km
2. Damage Length:
3. Nature of Damage (Length Wise) (i) Breach :-
(ii) Crust Damage :-
(iii) Only Flank Damage:-
Whether troffic fully/Dowling
4. Details of Restoration:
(i) Material Being Used in Restoration: - Onlow both, Local Sand Ec bogs rope
(ii) Equipment/Tools Being Used in Restoration Works:- てnochoと JCD
(iii) Restored Length In open Area:-
In habitation Area:-
(iv) If Restoration work done in habitation Area give Reason:-
B. For Bridge (Size of Bridge/Culvert)
(1) Damage Location/Chainage :-
(2) No. of Span Damage:-
(3) Length of Span:-
(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage):-
(5) Details of Restoration:-
(i) Material Being Used in Restoration:-
(ii) Equipment/Tools Being Used in Restoration Works :-
(iii) Restored Length:-
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Satisfactory
1 cm 5/21/24
Signature of Inspector
(Official Seal)
Official Seal)