

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD, works Division - Araria

Name of Block/Road :- Sikari Primary School (Dom Chauk Fak) to Asimahi Tola

A. For Road

1. Damage Location/Chainage :- 735.0 M

2. Damage Length :- 42.00 M

3. Nature of Damage (Length Wise)

(i) Breach :- Breach

(ii) Crust Damage :- crust damage

(iii) Only Flank Damage :-

whether traffic fully/Partialiy obstructed :-

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Local Sand Bamboo, Ec Bags, Brick Bats

(ii) Equipment/Tools Being Used in Restoration Works :-

Tractor with Trolley, JCB Roller etc

(iii) Restored Length

In open Area :-

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

11/11/21

Signature of Inspector
(Official Seal)