INSPECTION REPORT FOR MOTORABLE WORK

TIADI DO I a compression de la compression della
Name of PIUs:- EE RWA Works Division Anonia
Name of Block/Road: - Jukinat / Knuti Gate PWD Harijan Tola- Polari
A. For Road
1. Damage Location/Chainage: 0.01 km, 0.05 km, 0.6 Km, 0.82 km, 0.95 km
2. Damage Length: 76.1m
3. Nature of Damage (Length Wise) (i) Breach :- Breach Danage
(ii) Crust Damage: - Crust Damage
(iii) Only Flank Damage :-
whether traffic fully/Partialiy obstructed:- fully
4. Details of Restoration:
(i) Material Being Used in Restoration: - United both, GC Bags, Dam UV 6, Jan
(i) Material Being Used in Restoration: Brick bots, Ec Bags, Bambo of Joel Sand (ii) Equipment/Tools Being Used in Restoration Works: Tractor with trolley, TCB, Roller
(iii) Restored Length In open Area:-
In habitation Area:-
(iv) If Restoration work done in habitation Area give Reason :-
B. For Bridge (Size of Bridge/Culvert)
(1) Damage Location/Chainage :-
(2) No. of Span Damage:-
(3) Length of Span:-
(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage):-
(5) Details of Restoration:-
(i) Material Being Used in Restoration:-
(ii) Equipment/Tools Being Used in Restoration Works:-
(iii) Restored Length:-
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Satisfactory
Tano de l'Ilm
Signature of Inspector
(Official Seal)