

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD Works Division Anaria	
Name of Block/Road :- Takihat / Motiyari Mogra Mbsy idgah to Majgama Gihat Thakun to Rest part	
A. For Road	
1. Damage Location/Chainage :- 0.5 km, 0.7 km, 1.05 km, 1.7 km, 1.6 km	
2. Damage Length :- 192.7 m	
3. Nature of Damage (Length Wise)	(i) Breach :- Breach damage
	(ii) Crust Damage :- Crust damage
	(iii) Only Flank Damage :-
whether traffic fully/Partialiy obstructed :- fully	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :- local sand, Ec bags, Brick bat Dambos etc	
(ii) Equipment/Tools Being Used in Restoration Works :- 192.7	
(iii) Restored Length	In open Area :-
	In habitation Area :-
(iv) If Restoration work done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttment/Wing Wall/Approach Road Damage) :-	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment/Tools Being Used in Restoration Works :-	
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory	

6/11/24

19/11/24
Signature of Inspector
(Official Seal)