

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD Works Division Ananig	
Name of Block/Road :- Kumakatta / Primary School Madhubani to North Musche tota Dumoria	
A. For Road	
1. Damage Location/Chainage :-	0.800 km
2. Damage Length :-	40m
3. Nature of Damage (Length Wise)	(i) Breach :- (ii) Crust Damage :- crust Damage (iii) Only Flank Damage :- flank cutting
whether traffic fully/Partially obstructed :- fully	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :- local sand, EC bags, Bamboo, Brick bats etc	
(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with trolley, Roller, JCB etc	
(iii) Restored Length	In open Area :- 40m In habitation Area :-
(iv) If Restoration work done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttment/ Wing Wall/Approach Road Damage) :-	
(5) Details of Restoration :-	
(i) Material Being Used in Restoration :-	
(ii) Equipment/Tools Being Used in Restoration Works :-	
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory	

Prasad
11/11/24
DE

18/11/24

Signature of Inspector
(Official Seal)