## INSPECTION REPORT FOR MOTORABLE WORK

ame of PIUs:- RIND WORKS	DIVISION PRABHATA ROAD TO JOTHOO
ame of Block / Road :- ISMAILPO	DIVISION, NAVGHOME THE OR/BREGARA PRABHATA ROAD TO JOTHGO
. For Road	1-0-200 M, 1400, 2100, 5600, 5650, 5675, 675, 670, 5675, 6700 M, 1400 M, 1800, 6300, 6320 M, 1800
Damage Location / Chainage:	(300 M) 6) 10 1 6300 1
. Damage Length: 220 M	1.1917
. Nature of Damage (length wise)	(i) Breach :- 18 M (ii) Crust Damage :- 202 M
	(ii) Crust Damage
	ructed Fully Obstructed.
whether traffic fully/Partialily obstr	ructed fully obtion
4. Details of Restoration;	2 0.40 1
4. Details of Restoration,  (i) Material Being Used in Restoration	in Restoration Works: Front End Loader, Rollen.  In open Area: 220 M
(ii) Equipment / Tools being Used	III Restoration
(iii) Restored length	п орен т
	In habitation Area:-
(iv) if Restoration work done in ha	abitation Area give Reason.
B. For Bridge (Size of Bridge / C	Culvert)
1. Damage Location / Chainage:	· · · · · · · · · · · · · · · · · · ·
2. No. of Span Damage :-	
	L.D. J. Domera)
4 Nature of Damage (Pier / Abutr	ment/Wing wall/Approach Road Damage) —
5. Details of Restoration :	
(i) Material Being Used in Restor	ration:
(ii) Equipment / Tools being Use	d in Restoration Works:
(iii) Restored length	In open Area :-
	In habitation Area :-

14/11/24 14/11/24 A 14/11/24

Shirl or

Signture of Inspector

(Officail Seal)

Executive Engineer

RWD Works Division

BANKA-1