

Inspection Report For Flood Damage Report

Date

- 1 Name of PIUs : Work Division Munger
- 2 Name of Block/ Road : Bariyarpur/ L026-T01 to Gosaichak (Track 3)
- A For Road :- Road
- 1 Damage Location/ Chainage : Road near Rishikund hault /CH 120-130,CH 270-290
- 2 Damage Length : 18.35 M
- 3 Nature of Damage : Breaches Due Flood of water cross away to road and the road portion
- 4 Details of Restoration Works : Brick bats filling in Breaches part of road. Filled with brick bats for motorable Work.
- i Material being used in Restoration works : Brick bats , Hume pipe 1000 dia
- ii Equipments/ Tools being used in Restoration works : JCB, Tractor, Roller etc..
- iii Procedure taken up in Restoration works : As per SOP
- iv Restored Length : 18.35 M
- B For Bridge : NA
- 1 Damage Location/ Chainage : NA
- 2 Damage Length : NA
- 3 Nature of Damage : NA
- 4 Details of Restoration Works : NA
- i Material being used in Restoration works : NA
- ii Equipments/ Tools being used in Restoration works : NA
- iii Procedure taken up in Restoration works : NA
- iv Restored Length : NA

Signature of

JE

/ AE

/ EE

Inspector Signature Engineer
RWD Works Division
Lakhisarai