

## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD, works Division- Asaria

Name of Block/Road :- Asaria / T01 to Modhipura.

### A. For Road

1. Damage Location/Chainage :- 0.980 km, 0.980 km

2. Damage Length :- 9.81 meter

3. Nature of Damage (Length Wise) (i) Breach :- Breach cutting.  
(ii) Crust Damage :- —  
(iii) Only Flank Damage :- —

whether traffic fully/Partially obstructed :- fully damage

### 4. Details of Restoration :-

(i) Material Being Used in Restoration :- Local sand, Bamboo, EC Bag, Brick Bats, etc

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with fork, TCB, roller, etc

(iii) Restored Length

In open Area :- 9.81 mtr.

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

### B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/  
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Signature of Inspector  
(Official Seal)

Cupk  
11/11/24  
An