

## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RHD, Works Division - Awaria  
 Name of Block/Road :- Jopihat / 701 to Kakan East Bhadauna

### A. For Road

1. Damage Location/Chainage :- At ch. 0.300 km

2. Damage Length :- 22 mtr

3. Nature of Damage (Length Wise) (i) Breach :- Breach Damage  
 (ii) Crust Damage :- crust Damage  
 (iii) Only Flank Damage :-

whether traffic fully/Partialiy obstructed :-

### 4. Details of Restoration :-

(i) Material Being Used in Restoration :- Local sand, Bambr, EC Bag, Brick Bats, etc

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with folley, JCB, Rollers, etc

(iii) Restored Length In open Area :- open Area  
 In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

### B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/  
 Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

11/11/24  
 02

6/11/24

Signature of Inspector  
 (Official Seal)