

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RHD, Meads Division - Araria
 Name of Block/Road :- Araria / Bizi Chowk to Dhasamganj

A. For Road

1. Damage Location/Chainage :- 1.380 km, 1.385 km, 1.400 km, 1.450 km, 1.455 km

2. Damage Length :- 72.90 mtr.

3. Nature of Damage (Length Wise)

| | |
|----------------------------|----------------|
| (i) Breach :- | Breach cutting |
| (ii) Crust Damage :- | Crust damage. |
| (iii) Only Flank Damage :- | — |

whether traffic fully/Partially obstructed :- fully.

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Local Sand, Bamboo, EC Bags, Brick Bats, etc

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with roller, JCB, Roller, etc.

(iii) Restored Length

| | |
|-----------------------|------------|
| In open Area :- | 72.90 mtr. |
| In habitation Area :- | |

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

Cupre
11/11/24
AV

Signature of Inspector
 (Official Seal)