INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:- EE RWA Works Birlsign Anania	
Name of PIUs:- EE RWD Works Dirloion Anonia Name of Block/Road:- Palasi / Denga Chowk to Suksena Rolum	víc
A. For Road	Ju
1. Damage Location/Chainage:- 0-820 km, 1-200 km	
2. Damage Length: 77m	
3. Nature of Damage (Length Wise) (i) Breach :-	
(ii) Crust Damage :-	
(iii) Only Flank Damage :-	
whether traffic fully/Partialiy obstructed:-	
4. Details of Restoration:-	
(i) Material Being Used in Restoration: - Price loto, Iscal Sand Ec lo	goo
(i) Material Being Used in Restoration: - Drick lots Incol Sand Ec (ii) Equipment/Tools Being Used in Restoration Works: - Trackor JCD	
(iii) Restored Length In open Area:-	
In habitation Area:-	
(iv) If Restoration work done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage:-	
(2) No. of Span Damage:-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttment/	
Wing Wall/Approach Road Damage):-	
(5) Details of Restoration:-	
(i) Material Being Used in Restoration :-	
(ii) Equipment/Tools Being Used in Restoration Works :-	
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Satisfactory	
المراج ال	
Signature of Inspector (Official Seal)	
σv	