

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD Works Division Agarfa
Name of Block/Road :- Sikti/Parasiya Dom Sudak to Padasiya Pethon Tola

A. For Road

1. Damage Location/Chainage :- 812 m

2. Damage Length :- 37.40 m

3. Nature of Damage (Length Wise) (i) Breach :- Breach
(ii) Crust Damage :-
(iii) Only Flank Damage :-

whether traffic fully/Partialiy obstructed :-

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Local Sand, Bamboo, EC Bags, Bridge Balz etc

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with Tolly, JCB, Roller etc

(iii) Restored Length

In open Area :-

In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

20/11/24

20/11/24
Signature of Inspector
(Official Seal)