

Inspection Report For Flood Damage Report

Date

- 1 Name of PIUs : Work Division Munger
- 2 Name of Block/ Road : BARIYARPUR/ L-032 to Laxmipur-Bind Tola
- A For Road : Road
- 1 Damage Location/ Chainage : 0.70 Km part of road submerged in water during the flood period CH-400 to CH-700
- 2 Damage Length : 290 M
- 3 Nature of Damage : Breaches Due to Flood of water cross away to road and the road portion damaged
- 4 Details of Restoration Works : Brick bats filling in Breaches part of road. Filled with brick bats & Local Sand for motorable Work.
- i Material being used in Restoration works : Brick bats , Local Sand
- ii Equipments/ Tools being used in Restoration works : JCB, Tractor, Roller trailer etc..
- iii Procedure taken up in Restoration works : As per SOP
- iv Restored Length : 290 M
- B For Bridge : NA
- 1 Damage Location/ Chainage : NA
- 2 Damage Length : NA
- 3 Nature of Damage : NA
- 4 Details of Restoration Works : NA
- i Material being used in Restoration works : NA
- ii Equipments/ Tools being used in Restoration works : NA
- iii Procedure taken up in Restoration works : NA
- iv Restored Length : NA

Signature of

JE

JE

/ AE

/ EE

Inspt. Signature

Executive Engineer
RWD Works Division
Lakhisarai