

# INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :-

Name of Block/ Road :- Shambhuganj/Pakarinya More Rampur Dadhi to Pakariya  
Uttar Talq.

A. For Road

1. Damage Location/ Chainage : Ch-0.556 to 0.565 km and 0.580 to 0.606 km

2. Damage length : 4-1 M. (0.041 KM) 15m and 26m

3. Nature of Damage (length wise)

(I) Branch :-

(II) Crust Damage :- 4-1 M

(III) Only flank Damage :- 4-1 M

Whether traffic fully/ partially obstructed

4. Details of Restoration :

(i) Material Being Used in Restoration :

Brick-Bats, Sand Bags.

(ii) Equipment/ Tools being Used in Restoration Works :

(iii) Restored length

41 M

In open Are :- 41 M.

in habitation Area :-

(iv) If Restoration work done in habitation Area Give Reason :-

B. For Bridge (Size of bridge/ Culvert)

1. Damage Location / Chainage :

2. No. of Span Damage :-

3. Length of Span :-

4. Nature of Damage (Pier/ Abutment/ Wing wall/ Approach Road Damage)

5. Details of Restoration :

(i) Material being Used in Restoration :

(ii) Equipment/ Tools being used in Restoration Works :

(iii) Restored length

In open Are :-

in habitation Area :-

Overall Grade of Restoration Work (Satisfactory / Unsatisfactory) Satisfactory.

SE  
13.11.24  
JE

13/11/24  
AC

Pitaw  
13.11.24  
E/E

13/11/24  
कार्यपालक अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रमण्डल बाँका-02