INSPECTION REPORT FOR MOTORABLE WORK

Vame of Block/Road:- Palas / North Prince Charter that the phalle book to be
. Damage Location/Chainage :-
Damage Length :-
8. Nature of Damage (Length Wise) (i) Breach :-
(ii) Crust Damage :-
(iii) Only Flank Damage :-
obstruct
1) Material Being II
(1) Waterial Being Used in Restoration: Local Land, bambon, EC bog, Both bats, reple
(ii) Equipment/Tools Being Used in Restoration Works:- JCB, Frankow,
(iii) Restored Length In open Area:-
In habitation Area:-
(IV) If Restoration work done in habitation Area give Reason:
B. For Bridge (Size of Bridge/Culvert)
(1) Damage Location/Chainage:-
(2) No. of Span Damage:-
(3) Length of Span :-
(4) Nature of Damage (Pier/Abuttment/ Wing Wall/Approach Road Damage):-
(5) Details of Restoration:-
(i) Material Being Used in Restoration:-
(ii) Equipment/Tools Being Used in Restoration Works:-
(iii) Restored Length :-
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Sahafed
In Machinal Company

(Official Seal)

