INSPECTION REPORT FOR MOTORABLE WORK

Jame of PIUs:- EE RWA WUYKO Divisies Anguia
Jame of PIUs: - EE RWA WUYKO Division Anania Jame of Block/Road: - Polasi / Pipna Dijwan Gast to Protto bani to
. For Road
Damage Location/Chainage:- 0.600 km
Damage Length: 21 m
. Nature of Damage (Length Wise) (i) Breach :-
(ii) Crust Damage:-
(iii) Only Flank Damage :-
whether traffic fully/Partially obstructed:- Fully
LUCIALIS OF Restoration .
1) Material Being Used in Restoration: Brich both Incol Sand Ec lago etc
i) Material Being Used in Restoration: Brich both, Incol Sand, Ec logs et ii) Equipment/Tools Being Used in Restoration Works: Tractor, Top etc.
iii) Restored Length In open Area:-
In habitation Area:-
iv) If Restoration work done in habitation Area give Reason :-
B. For Bridge (Size of Bridge/Culvert)
1) Damage Location/Chainage:-
2) No. of Span Damage:-
(3) Length of Span:-
(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-
(5) Details of Restoration:-
(i) Material Being Used in Restoration:-
(ii) Equipment/Tools Being Used in Restoration Works :-
(iii) Restored Length :-
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Sahafell
Jus 3/11/1-4
Signature of Inspector (Official Seal)