## INSPECTION REPORT FOR MOTORABLE WORK

CDILL ON THO TOKABLE WORK	
Name of Plus: - EE RND, works Drision - Amore	
Name of PIUs: - EE RND, mosts Dirision - Arasia Name of Block/Road: - Siptifforchayat Bhaman Parasia to Pagaria	
A. For Road	Magn
1. Damage Location/Chainage: 49M, 470M, 850M	
2. Damage Length :- 2 28.30 M	
3. Nature of Damage (Length Wise) (i) Breach :- Oreach	
(ii) Crust Damage: - Crust Damage &	Breau
(iii) Only Flank Damage :- whether traffic fully/Partially obstructed :-	Marine Marine Marine
4. Details of Restoration:	-
i) Material Being Used in Restoration: Local Sand, Bamboo, EC Bag, E	22/01/2 0
The instantion of the state of	4
ii) Equipment/Tools Being Used in Restoration Works:-  Tractor with Trolly: Roller, JCB est	
iii) Restored Length In open Area :-	
In habitation Area:-	
v) If Restoration work done in habitation Area give Reason:-	
3. For Bridge (Size of Bridge/Culvert)	
1) Damage Location/Chainage:-	
2) No. of Span Damage:-	
3) Length of Span :-	
1) Nature of Damage (Pier/Abuttment/	
Ving Wall/Approach Road Damage):-	
i) Details of Restoration:-	and the second
) Material Being Used in Restoration :-	
i) Equipment/Tools Being Used in Restoration Works:-	
ii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Satisfactory	tory
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):-Satisfactory	

900

Signature of Inspector (Official Seal)