INSPECTION REPORT FOR MOTORABLE WORK

Name of Plus:- RIND INDRA	N 1/.
Name of Block / Road :- Goodhur	Pavision, Navgachiya. Road No-19 Saidpur More To Buddhu Chawk
A. For Road	7 / () () () () () () () () () (
1. Damage Location / Chainage:	MASC- 07, MO2-0
2. Damage Length: 230 M	
3. Nature of Damage (length wise)	(i) Breach :- 6 M
	(ii) Crust Damage:- 15079
	(iii) Only Flank Damage 7 A M
whether traffic fully/Partialily obstr	
4. Details of Restoration;	4
(i) Material Being Used in Restorat	ion: Ec bag, was sand
(ii) Equipment / Tools being Used i	n Restoration Works: foutor, then water.
(iii) Restored length	In open Area: 230M
The state of the second	In habitation Area :-
(iv) if Restoration work done in hab	pitation Area give Reason :- —
B. For Bridge (Size of Bridge / Cu	ılvert)
1. Damage Location / Chainage:	
2. No. of Span Damage :-	
3 Length of Span —	
4 Nature of Damage (Pier / Abutme	ent/Wing wall/Approach Road Damage)
5. Details of Restoration:	-
(i) Material Being Used in Restorat	ion:
(ii) Equipment / Tools being Used i	n Restoration Works : —
(iii) Restored length	In open Area:-
	In habitation Area :-
Overall Grade of Restoration Work	(Satisfactory / Unsatisfactory) safisfactory.
	, ,

14/11/024 J.E 14/11/24 In/m/m

Signture of Inspector

Externion

RWD Works Division

BANKA-1