	Inspection Report For Flood Damage Work
)a]	Name of PiUs: Grhalgay - 2
	Name of Block/Road: Jacki Rai Ice Tola To Parelayet Bhanean.
1	Damage Location / Chainage: 860 H to 867 H
	Damage Length: 7 4.
3	Nature of Damage: Heavy Rais / Flord
4	Details of Restroration Works:
	i. Material being used in Restoration Works: Brick Bats
	ii Equipments / Tools being used in Restoration Works: JCB, Tracker, Troli, Rolles etc
	iii Procedure taken up in Restoration Works:
	iv Restored Length:
В	For Bridge
1	Damage Location / Chainage:
2	Damage Length:
3	Nature of Damage:
4	Details of Restroration Works:
	Nature of Damage: Details of Restroration Works: i. Material being used in Restoration Works: EXECUTIVE ENGINEER EXECUTIVE ENGINEER
	ii Equipments / Tools being used in Portoration Works

S.E

iii Procedure taken up in Restoration Works:

iv Restored Length: