

## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD Works Division Anantnag							
Name of Block/Road :- Jukhot / Chainpur Kanya Vidyalaya Balingorhi Makolgaon to Wajidpur Primary Road to 4							
<b>A. For Road</b>							
1. Damage Location/Chainage :-	1.1 km, 1.05 km						
2. Damage Length :-	38 m						
3. Nature of Damage (Length Wise)	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>(i) Breach :-</td> <td>Breach Damage</td> </tr> <tr> <td>(ii) Crust Damage :-</td> <td>Crust Damage</td> </tr> <tr> <td>(iii) Only Flank Damage :-</td> <td></td> </tr> </table>	(i) Breach :-	Breach Damage	(ii) Crust Damage :-	Crust Damage	(iii) Only Flank Damage :-	
(i) Breach :-	Breach Damage						
(ii) Crust Damage :-	Crust Damage						
(iii) Only Flank Damage :-							
whether traffic fully/Partially obstructed :- Fully							
<b>4. Details of Restoration :-</b>							
(i) Material Being Used in Restoration :- Local Sand, Bamboo, EC bag, Brick bat							
(ii) Equipment/Tools Being Used in Restoration Works :- JCB, Roller, Tractor with trolley							
(iii) Restored Length	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>In open Area :-</td> <td>open Area</td> </tr> <tr> <td>In habitation Area :-</td> <td></td> </tr> </table>	In open Area :-	open Area	In habitation Area :-			
In open Area :-	open Area						
In habitation Area :-							
(iv) If Restoration work done in habitation Area give Reason :-							
<b>B. For Bridge (Size of Bridge/Culvert)</b>							
(1) Damage Location/Chainage :-							
(2) No. of Span Damage :-							
(3) Length of Span :-							
(4) Nature of Damage (Pier/Abuttment/Wing Wall/Approach Road Damage) :-							
(5) Details of Restoration :-							
(i) Material Being Used in Restoration :-							
(ii) Equipment/Tools Being Used in Restoration Works :-							
(iii) Restored Length :-							
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory							

6/11/24

Signature of Inspector  
(Official Seal)