INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:- EE RWA WORKS Division Anonla	
Name of Block/Road: - Juli Lot Uda Wayasi REO Road Prothonic	
Name of PIUs:- EE RWA Works Division Anang Name of Block/Road:- Junihot Uda Wayasi REO Road Prothoic A. For Road Vidyalay kurmi	
1. Damage Location/Chainage:- 0, 400 Km	
2. Damage Length: 79. Tmt	
3. Nature of Damage (Length Wise) (i) Breach :-	
(ii) Crust Damage: - Crust Damage	
(ii) Crust Damage:- Crust Samage (iii) Only Flank Damage:- Flank Samage	
whether traffic fully/Partially obstructed:- 10110 114	
4. Details of Restoration:	
(ii) Material Being Used in Restoration: - facel Sand, Bamboo, Ec bag, Brick (iii) Equipment/Tools Being Used in Restoration Works: - Tractor with holley, Jc B (iii) Restored Length In open Area: In habitation Area:	botete
(ii) Equipment/Tools Being Used in Restoration Works:- Tractor with tralley TCR	Roller of
(iii) Restored Length In open Area:-	
In habitation Area:-	
(iv) If Restoration work done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage :-	
(3) Length of Span:-	
(4) Nature of Damage (Pier/Abuttment/	
Wing Wall/Approach Road Damage):-	
(5) Details of Restoration:-	
(i) Material Being Used in Restoration:-	
(ii) Equipment/Tools Being Used in Restoration Works :-	
(iii) Restored Length :-	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Schofactory	111,
M. V.V. 1M	
Jan 10/11/	
Signature of Inspector	
Official Seal)	
	V.