

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE Road, wards dindar Arasia.

Name of Block Road :- Arasia / Mahabir Mandir to Tarahasi Gathi Tola

A. For Road

1. Damage Location/Chainage :- 0+03 0.37 km

2. Damage Length :- 32 mtr.

3. Nature of Damage (Length Wise)

(i) Breach :-	<u>Breach cutting.</u>
(ii) Crust Damage :-	<u>Crust damage</u>
(iii) Only Flank Damage :-	

whether traffic fully/Partialiy obstructed :- fully.

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Local Sand, Bamboo, EC Bag, Brick Bats, etc

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with trolly, SCR, Pallets, etc

(iii) Restored Length

In open Area :-	<u>32 mtr.</u>
In habitation Area :-	

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-


(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory


Signature of Inspector
(Official Seal)

Cupia
11/11/24
132