

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- GE RWD Works Division Araria

Name of Block/Road :- Jakhoh / Manadpur fulpur PMGSY to Jogindra river

A. For Road

1. Damage Location/Chainage :- 0.700 km

2. Damage Length :- 18 mtr

3. Nature of Damage (Length Wise)

(i) Breach :- <u>Breach Damage</u>
(ii) Crust Damage :- <u>Crust Damage</u>
(iii) Only Flank Damage :-

whether traffic fully/Partialiy obstructed :- fully

4. Details of Restoration :-

(i) Material Being Used in Restoration :- EC bag, brick bats, local sand, Bamboo

(ii) Equipment/Tools Being Used in Restoration Works :- Roller, JCB, Tractor with trolley

(iii) Restored Length

In open Area :- <u>18 mt open Area</u>
In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

6/11/24
me

6/11/24

6/11/24
Signature of Inspector
(Official Seal)