## INSPECTION REPORT FOR MOTORARI E WORK

me of PIUs:- (w) (	RT FOR MOTORABLE WORK
me of Block/Road :- Kaul a	anui Road to Baskeerd kachlus tile
2.0	elaran
Tor Road	eraran
Damage Location/Chainage :-	2.40 KM
Damage Length: 20	1.0m
Nature of Damage (Length Wise)	(i) Breach:- 20.0m
#P	(ii) Crust Damage:- 20.0 m
	(iii) Only Flank Damage :-
whether traffic fully/Partially obstruction	
. Details of Restoration :-	
i) Material Being Used in Restoration	on: Brick botk, GSB, H.P
(ii) Equipment/Tools Being Used in	Restoration Works: - Tractor, JCB.
(iii) Restored Length .	In open Area:- 20, om
	In habitation Area :-
(iv) If Restoration work done in hab	itation Area give Reason :-
B. For Bridge (Size of Bridge/C	ulvert)
(1) Damage Location/Chainage:-	
(2) No. of Span Damage :-	
(3) Length of Span :-	
(4) Nature of Damage (Pier/Abuttm	ent/
Wing Wall/Approach Road Damage	):-
(5) Details of Restoration:-	
(i) Material Being Used in Restorati	on:-
(ii) Equipment/Tools Being Used in	Restoration Works :-
(iii) Restored Length :-	
	-k (Satisfactory/I Insatisfactory)
Overall Grade of Restoration Wo	rk (Satisfactory/Unsatisfactory) :-

8011.24 8E AEI

Signature of Inspector (Official Seal)

4. Wirman