## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:- RWD Works	Division, Naygochligo.
Name of Block / Road :- Goldburs /	Division, Navgochtigo. Shyandeo Claudlay Hruse To RCD Road No-14
A. For Road	
1. Damage Location / Chainage: 6	-180M
2. Damage Length: 275 m	
3. Nature of Damage (length wise)	
	(ii) Crust Damage :-
	(iii) Only Flank Damage - 275 M
whether traffic fully/Partialily obstr	ucted - partiality obstructed
4. Details of Restoration;	
(i) Material Being Used in Restorati	ion: Sand Bag
	n Restoration Works: Front end Lower
(iii) Restored length	In open Area:- 275 M
	In habitation Area:-
(iv) if Restoration work done in hab	bitation Area give Reason :
B. For Bridge (Size of Bridge / Cu	ulvert) –
1. Damage Location / Chainage :	
2. No. of Span Damage :-	
3 Length of Span	
4 Nature of Damage (Pier / Abutme	ent/Wing wall/Approach Road Damage) 🔍
5. Details of Restoration:	
(i) Material Being Used in Restorat	ion:
(ii) Equipment / Tools being Used i	in Restoration Works:
(iii) Restored length	In open Area:-
	In habitation Area :-
Overall Grade of Restoration Work	(Satisfactory / Unsatisfactory) Suffsfactory.

14/11/024 5.6 METOA EMPINI.

Signture of Inspector

(Officail Seal)

Executive Engineer

RWD Works Division

BANKA-1