INSPECTION REPORT FOR MOTORABLE WORK

Jame of PIUs:- EE RW/	> Warko Nichia Amia	7
Jame of Block/Road :- Polosi	TOO NATOR TO A A LANGE TO	1 /2 /2 /2 /4 /2
, For Road	> Works Sivision Anania 1702 NHJ27 E Raw Chowk to Pur noc	VIA DUMONO
Damage Location/Chainage :-		_
Damage Length :-	1.2.00 Km, 0,000 Km	4
	1-1-m-7/m	
Nature of Damage (Length Wise		4
	(ii) Crust Damage :-	_
hether traffic fully/Partialiy obstru	(iii) Only Flank Damage :-	_
Details of Restoration:-	acted:- Fully	-
Material Being Used in Restorati	ion: - Brick bots, Local Sand, Bombu	ete
Equipment/Tools Being Used in	Restoration Works: - Tractor, Jos	
i) Restored Length	In open Area:-]
	In habitation Area:-	
) If Restoration work done in hab	itation Area give Reason :-	
For Bridge (Size of Bridge/C	'ulvert)	
Damage Location/Chainage :-	1	
No. of Span Damage :-	N/A	
Length of Span :-		
Nature of Damage (Pier/Abuttment/		1
ng Wall/Approach Road Damage):-		
Details of Restoration:-		
Material Being Used in Restoration		
Equipment/Tools Being Used in I	Restoration Works:-	
Restored Length:-		
		,
erall Grade of Restoration work	(Satisfactory/Unsatisfactory):- Satisfactory	
	Tunes Millow	
	Signature of Inspector	
100 mil 8 1	(Official Seal)	