## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs: - EE RWD, works Division - Aranga	
Name of Block/Road:- Kushakatta TO2- Nepal Border Garaia Gash to	ZHM
A. For Road	AND
1. Damage Location/Chainage: - 2 3.50 km, 23.50 km, 23.50 km, 23.50 km, 23.50 km	
2. Damage Length: 155 mts	
3. Nature of Damage (Length Wise) (i) Breach: Breach Cuffing	
(ii) Crust Damage: - Crust darlage.	
(iii) Only Flank Damage:-	
whether traffic fully/Partialiy obstructed:- fully.	
4. Details of Restoration:-	
(i) Material Being Used in Restoration: - Local Sand, Bamboo, & Bag, Brick Buts, e	<del>Le</del>
(i) Material Being Used in Restoration: Local Sand, Bamboo, FC Bag, Brick Buts, e (ii) Equipment/Tools Being Used in Restoration Works: Fractor with trolley, JCB, Rolle	riefe
(iii) Restored Length In open Area:- 155 mts.	
In habitation Area:-	
(iv) If Restoration work done in habitation Area give Reason:-	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage:-	
(3) Length of Span:-	
(4) Nature of Damage (Pier/Abuttment/	
Wing Wall/Approach Road Damage):-	
(5) Details of Restoration:-	
(i) Material Being Used in Restoration:-	
(ii) Equipment/Tools Being Used in Restoration Works:-	
(iii) Restored Length :-	
1 (G. 4: - G. etamy/ Ingetis factory) - Satillactory	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory): -Satisfactory	
Giometros of Inspector	
Signature of Inspector (Official Seal)	