## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:- EE RWD LOVED Divinion Anania
Name of Block/Road: - Jokingt   Artiya Chobaniya PMGSY Baro Chan to
Name of Block/Road: - Jokinot   Artiya Dhobaniya PMASY Bano Dhan to  A. For Road  Kachon chop Artiya
1. Damage Location/Chainage: At ch 1.8 km, 1.1 km
2. Damage Length: 109 mtv
3. Nature of Damage (Length Wise) (i) Breach :-
(ii) Crust Damage :-
(iii) Only Flank Damage :-
whether traffic fully/Partialiy obstructed:-
4. Details of Restoration:-
(i) Material Being Used in Restoration:-
(ii) Equipment/Tools Being Used in Restoration Works:-
(iii) Restored Length In open Area:-
In habitation Area:-
(iv) If Restoration work done in habitation Area give Reason :-
B. For Bridge (Size of Bridge/Culvert)
(1) Damage Location/Chainage: At Ch 1.8 Km, 1.1 Km
(2) No. of Span Damage :- NO
(3) Length of Span:-
(4) Nature of Damage (Pier/Abuttment/Wing Wall/Approach Road Damage):- Approach Inad damage
Wing Wall/Approach Road Damage):- Hpp10ach 110ad damage.
(5) Details of Restoration:-
(i) Material Being Used in Restoration: - focal Sand, Ramboo, Ec bag brick bet etc (ii) Equipment/Tools Being Used in Restoration Works: - Tractor with trolley, 708 koller
(ii) Equipment/Tools Being Used in Restoration Works: - Tractor with folley 708 loller
(iii) Restored Length: 109 mt
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Sa has factory
( 5 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Signature of Inspector  (Official Seal)
Signature of Inspector