

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :-		EE RWD Works Division Anantnag	
Name of Block/Road :-		Jukihott (Trianpul) Dubba Majhuna PMGSY Road	
A. For Road		Majhuna to (Dandu) Rori Tek	
1. Damage Location/Chainage :-		0.500 km, 0.950 km	
2. Damage Length :-		42m	
3. Nature of Damage (Length Wise)		(i) Breach :- Breach Damage (ii) Crust Damage :- Crust Damage (iii) Only Flank Damage :-	
whether traffic fully/Partially obstructed :- Fully			
4. Details of Restoration :-			
(i) Material Being Used in Restoration :- Brick bats, Local sand, EC bags, Bamboo etc			
(ii) Equipment/Tools Being Used in Restoration Works :- Tractor with Trolley, JCB Roller			
(iii) Restored Length		In open Area :- open Area In habitation Area :-	
(iv) If Restoration work done in habitation Area give Reason :-			
B. For Bridge (Size of Bridge/Culvert)			
(1) Damage Location/Chainage :-			
(2) No. of Span Damage :-			
(3) Length of Span :-			
(4) Nature of Damage (Pier/Abuttment/Wing Wall/Approach Road Damage) :-			
(5) Details of Restoration :-			
(i) Material Being Used in Restoration :-			
(ii) Equipment/Tools Being Used in Restoration Works :-			
(iii) Restored Length :-			
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory			

9/11/24

Signature of Inspector
(Official Seal)