

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- R.W.D works Division Navgachhiya	
Name of Block / Road :- Ismailpur/Basagara Prabhata road to Jathgoving Near Bhini manfal Base to Kaho manfal Ghar-tak.	
A. For Road	
1. Damage Location / Chainage : 0-104, 280-310, 370-410	
2. Damage Length : 0.463 160M	
3. Nature of Damage (length wise)	(i) Breach :-
	(ii) Crust Damage :- 160M
	(iii) Only Flank Damage
whether traffic fully/Partialily obstructed → Fully obstructed.	
4. Details of Restoration :	
(i) Material Being Used in Restoration : Brick Bats	
(ii) Equipment / Tools being Used in Restoration Works : Front end Loader, Roller	
(iii) Restored length	In open Area :- 160M
	In habitation Area :- —
(iv) if Restoration work done in habitation Area give Reason :- —	
B. For Bridge (Size of Bridge / Culvert) —	
1. Damage Location / Chainage : —	
2. No. of Span Damage :- —	
3 Length of Span —	
4 Nature of Damage (Pier / Abutment/Wing wall/Approach Road Damage) —	
5. Details of Restoration : —	
(i) Material Being Used in Restoration : —	
(ii) Equipment / Tools being Used in Restoration Works : —	
(iii) Restored length	In open Area :- —
	In habitation Area :- —
Overall Grade of Restoration Work (Satisfactory / Unsatisfactory) satisfactory.	

CH
14/11/24
JE

ME
14/11/24

Shu
14/11/24
EE

Priyam
14/11/24
Signature of Inspector
(Officail Seal)
Executive Engineer
RWD Works Division
BANKA-1