## INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs:	I DIVISION, MAUMACHIA.
Name of Block / Road . 2 hours	A CHOWK [COZO-HH-31 TO MUTTS
A. For Road	chankhara (vR12)
	00-900, 1000-1005 m, 1050-1100, 1200-12C0
2. Damage Length: 97.80 m	
3. Nature of Damage (length wise)	
e (mgar vise)	(ii) Crust Damage :- 40 th
	(iii) Only Flank Damage 9017
whether traffic fully/Partialily obstr	
4. Details of Restoration;	10.11.00
(i) Material Being Used in Restorat	ion: Brick Ball
(ii) Equipment / Tools being Used i	n Restoration Works: Front End Loader
(iii) Restored length	In open Area:- 97.8019
	In habitation Area :-
iv) if Restoration work done in hab	oitation Area give Reason:- —
B. For Bridge (Size of Bridge / Cu	ılvert)
1. Damage Location / Chainage:	_
2. No. of Span Damage:-	
Length of Span	
Nature of Damage (Pier / Abutme	nt/Wing wall/Approach Road Damage)
. Details of Restoration:	-
) Material Being Used in Restorati	on: _
i) Equipment / Tools being Used in	n Restoration Works : —
iii) Restored length	In open Area :-
	In habitation Area :-
verall Grade of Restoration Work	(Satisfactory / Unsatisfactory) satisfactory
	- Latter of to La

ME 14/11/14 ee

14:11. 24 14:11. 24

Executive Engineer
RMD WORKS Division
BANKA-1