

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- <u>RWD REINWORKS DIVISION, NANGACHILYA</u>	
Name of Block / Road :- <u>GOPALPUR/LOBO - RCD ROAD SUNGATIA TO TINTANGA KARRAI (100m)</u>	
A. For Road	
1. Damage Location / Chainage : <u>30 - 100 m, 0-150 m, 100-250 m, 250-440m, 600-820m</u>	
2. Damage Length : <u>- 561 m</u>	
3. Nature of Damage (length wise)	(i) Breach :-
	(ii) Crust Damage :- <u>10 m</u>
	(iii) Only Flank Damage <u>551 m</u>
whether traffic fully/Partially obstructed - <u>Partially obstructed</u>	
4. Details of Restoration :	
(i) Material Being Used in Restoration : <u>- EC Bag, local sand, bamboo</u>	
(ii) Equipment / Tools being Used in Restoration Works : <u>Front end loader, Tractor</u>	
(iii) Restored length	In open Area :- <u>561 m</u>
	In habitation Area :-
(iv) if Restoration work done in habitation Area give Reason :-	
B. For Bridge (Size of Bridge / Culvert)	
1. Damage Location / Chainage :	
2. No. of Span Damage :-	
3 Length of Span	
4 Nature of Damage (Pier / Abutment/Wing wall/Approach Road Damage)	
5. Details of Restoration :	
(i) Material Being Used in Restoration :	
(ii) Equipment / Tools being Used in Restoration Works :	
(iii) Restored length	In open Area :-
	In habitation Area :-
Overall Grade of Restoration Work (Satisfactory / Unsatisfactory) <u>Satisfactory.</u>	

Sales
14/11/24
S.E

DA
14/11/24

3km
14/11/24
E.E

Priyam
14/11/24
Signature of Inspector
(Official Seal)
Executive Engineer
RWD Works Division
BANKA-1